




disconnect each of these loads and see which one fixes the rail

15v and 7v rail both are full with no lo
Something on 15v rail is dragging it d
Resistance is low because of tube file